Environmental Health & Safety Programs

Title: Hot Work Program	Document No.: OCS-401 Revision No.: 02 Date: March 20, 2023
	Approved By : Avraham Boruchowitz, CSP, CHMM

Title: Hot Work Program	Document No.: OCS-401 Revision No.: 02 Date: March 20, 2023
	Approved By : Avraham Boruchowitz, CSP, CHMM

Environmental Health &

Title: Hot Work Program

Document No.: OCS

Title: Hot Work Program	Document No.: OCS-401 Revision No.: 02 Date: March 20, 2023
	Approved By : Avraham Boruchowitz, CSP, CHMM

5. The employee/hot work operator will return the hot work permit to the supervisor after the task is complete or at the end of the work shift
6. The supervisor will then give the completed permit to EHS for recordkeeping.

6.0 Fire Prevention and Protection

When practical, objects welded or cut will be moved to a designated safe location. If the object cannot readily be moved, all movable fire hazards in the vicinity will be taken to a safe place. If possible, combustibles will be relocated at least 35 feet from the work site.

If the object welded or cut cannot be moved and if the fire hazards cannot be removed, then guards will be used to confine heat, sparks, and slag, and to protect immovable fire hazards.

If there are floor openings that cannot be closed, precautions will be taken to prevent combustible materials on the floor below from being exposed to sparks which might drop through the floor. The same precautions will be observed with cracks or holes in walls, open doorways and open or broken windows.
Suitable fire extinguishing equipment will be readily available.

Fire watchers are required whenever welding or cutting is performed in locations where any of the following conditions exist

Environmental Health & Safety Programs

Title: Hot Work Program	Document No.: OCS-401 Revision No.: 02 Date: March 20, 2023 Approved By : Avraham Boruchowitz, CSP, CHMM

Environmental Health & Safety Programs

Title: Hot Work Program

Document No.: OCS-401

Revision No.: 02 Date: March 20

Title: Hot Work Program	Document No.: OCS-401 Revision No.: 02 Date: March 20, 2023
	Approved By : Avraham Boruchowitz, CSP, CHMM

9.0 Protection of Personnel

9.1 General

A welder working on platforms, scaffolds, or runways will be protected against falling. This may be accomplished by the use of railings, safety harnesses, life lines, or other equally effective safeguards.

Welders will place welding cable and other equipment so that it is clear of passageways, ladders, and stairways.

9.2 Eye Protection

Helmets or hand shields will be used during all arc welding or arc cutting operations.

E

Environmental Health & Safety Programs

Title: Hot Work Program

Document No.:

Environmental Health & Safety Programs

Title: Hot Work Program	Document No.: OCS-401 Revision No.: 02 Date: March 20, 2023
	Approved By : Avraham Boruchowitz, CSP, CHMM

51.4773 1.4832 5.2 71 Tm0 1 7 Tf 0.1612 91 33 91

10.4.6 Cleaning Compounds

Indoors, Confined Space, and Outdoors: Because of their possible toxicity or flammability, appropriate precautions such as P D Q X I D F L Q V W U X F W L R Q V will be followed. Operations involving chlorinated hydrocarbons will be located so that vapors from these operations will not be drawn into the atmosphere surrounding the welding operation. In addition, trichloroethylene and perchloroethylene should be kept out of atmospheres penetrated by the ultraviolet radiation of gas-shielded welding operations.

10.4.7 Stainless Steel

Indoors, Confined Space, and Outdoors: Oxygen cutting, using either a chemical flux or iron powder or gas-shielded arc cutting of stainless steel, will be done using mechanical ventilation adequate to remove the fumes.

10.5 First-aid equipment

First-aid equipment will be available at all times. All injuries will be reported as soon as possible for medical attention. First aid will be rendered until medical attention can be provided.

11.0 Employee Training

11.1 – Initial Training

EHS will provide initial and refresher training to all employees that perform hot work activities. The supervisor is responsible for ensuring that all new employees receive training before conducting a task that meets the criteria of hot work operations as outlined in this program.

The initial training should include the following topics:

- Written program
- Hot work procedures, including how to obtain a permit
- Proper equipment operation
- Handling and storage of welding materials
- Compressed gas cylinder safety
- Fire watch
- Fire precautions
- Fire extinguisher training

Environmental Health & Safety Programs

Title: Hot Work Program

Document No.: OCS-401

Revision No.: 02 Date: March 20, 20

HOT WORK PERMIT

GENERAL INFORMATION		
Date:	Permit begins:	Permit ends:
Location of work:		
Equipment to be used:		
Person performing hot work:		
Description of work:		

FIRE SAFETY PRECAUTIONS CHECKLIST					
Hot work equipment in good repair.		Fire watch provided during and for at least 60 minutes after work.		Combustibles on other side of w moved.	
Fire extinguisher within 30 fee		Fire watch trained in use of fire extinguishers.		Exposed construction is noncombustible or covered.	
Combustible materials within 35 feet removed or protected with fire resistive material		Available sprinklers are operable.			